



# Parker Hannifin MSDE/ECBU

## Product Change Notification

**PCN7432019-47631-2**

Dear Customer,

Important information for your attention:  
Please find attached our Parker Hannifin PCN:

### Implementation of new display module in IQAN-MD4-7

- SUBJECT OF CHANGE:**
- New LCD-module.
  - Updated main board.
  - New SW version

**PRODUCT AFFECTED:** IQAN-MD4-7, part no.: 20077771

**REASON FOR CHANGE:** Due to EOL of some components on the LCD, the old Display module needed to be exchange. The new display module has equal or better performance compare to current Display module.  
Modifications to the main board are required to adapt to the new LCD module.

DESCRIPTION OF CHANGE:	OLD Display module	NEW Display module
New software version	5.01	5.04
Lowest SW version allowed	3.14	4.07.8

**IMPORTANT:** The unit prevents download of SW version 4.06 and older. Download of IQANdesign version 4.07.7 locks the unit and prevents further communication. If a unit is locked it can only be recovered by Parker production.

**TIME SCHEDULE:** Production start:  
S/N US: 1914040014  
S/N EU: 1914280023

**ASSESSMENT:** Besides software update there will be no other impact on form, fit, function, quality or reliability of the products affected.  
It is recommended to use SW version **4.07.15** or later.

**DOCUMENT HISTORY:** PCN7432018-47631-1: First edition, created 17 May 2019  
PCN7432018-47631-2: Added EU serial number

If you have any questions, please do not hesitate to contact your local Sales office.